


Figure 6.11: Peat Condition Assessment



- Turbine
- Site Boundary
- Infrastructure footprint
- Existing track
- Peat Condition Assessment**
- Peat Landslide Hazard and Risk Assessment (PLHRA)
- PCA**
- Category 2 - Modified
- Category 3 - Drained
- Category 4 - Actively
- Category 5 - Not peatland (peat less than 50cm depth and non-peat soils)